## **COLPAI Project Drop-In:** SITE PROGRESS & UPCOMING WORKS



### Site Progress

The works currently taking place on-site are primarily groundworks, these include:

- Reduce level dig and backfilling works in the residential building area adjacent to the London School of Fashion
- Unexploded Ordnance (UXO) probing works in the residential building area
- Concrete slab pour on the first floor of the residential building
- Groundworks and concrete pours in the school and school hall area

### www.colpai-project.co.uk | info@colpai-project.co.uk | 0800 772 0475



- Excavators filling muck away lorries
- Site-wide asbestos watching brief
- Site-wide air quality monitoring
- Site-wide environmental monitoring







# **COLPAI Project Drop-In:** MONITORING DATA


Now that demolition works on-site have been completed dust, noise and vibration monitoring activities on-site have been reduced. Monitors will remain in place at **Basterfield House and Hatfield House as the** construction works begin on-site.

The monitors are set within acceptable tolerance levels and we endeavour at all times to keep within the dust, noise and vibration control limits expected by the City of London and the London Borough of Islington. If any of the control limits are exceeded, the monitors will alert the site team so that early remedial action can be taken.

To date, the maximum vibration level recorded internally at Basterfield House was 0.8mm/s, which is considerably below the trigger level of 4mm/s.

Noise and dust levels remain within established limits. The on-site team will continue to monitor these results and make the monitoring data available on our noticeboard on the site hoardings.

www.colpai-project.co.uk | info@colpai-project.co.uk | 0800 772 0475









### To view the COLPAI Project Planning Condition Consultation boards visit:

www.colpai-project.co.uk/consultation

www.colpai-project.co.uk | info@colpai-project.co.uk | 0800 772 0475





